

Inspection Report (Periodic)

FolderID: IN2480
FormID: 5372088



Underhung Bridge Crane

Completed by: CES Technician on
04/15/2019

Location:	Main Street Plant
Area:	Shop
System Identifier:	NORTH CRANE. BC-A
Customer Unit ID:	H-1
Status:	Standard

Bridge Manufacturer:	North American
Bridge Capacity:	3 Ton
Bridge Serial #:	Unknown
Hoist Type:	Electric with Load Chain
Hoist Manufacturer:	CM Lodestar
Hoist Serial #:	980555
Hoist Model #:	9514NHMT
Hoist Capacity:	3 Ton

Priorities Found: ● 2 - Medium ● 50 - Good

Under Running Crane Runway

●	1. Support steel connections (building structure)	No Issue
●	2. Support beam and track conditions (bottom flange)	No Issue
●	3. Splice and alignment plates	No Issue
●	4. Hanger rod assembly	No Issue
●	5. End stops	No Issue
●	6. Sway and thrust bracing	No Issue
●	8. Electrification / Hardware	No Issue

Under Running Bridge

●	9. Frame/Structure condition	No Issue
●	10. Driver wheels	No Issue
●	11. Idler wheels	No Issue
●	12. End Trucks	No Issue
●	13. End Stops	No Issue
●	15. Lube / Oil	No Issue
●	16. Clearances	No Issue
●	17. Capacity labels	No Issue
●	18. Manufacture's identification	No Issue
●	19. Motors	No Issue
●	20. Electrical	No Issue
●	21. Tagline components / Festoon track condition	No Issue

All inspections are Visual Inspections only. The information contained herein is believed to be accurate and represents the Inspector's best interpretation of the conditions observed during the inspection. The proper operation, testing and maintenance of the equipment inspected is the continuing responsibility of the OWNER in accordance with ANSI B30.2.0 and section 1910.179 of OSHA.

Printed on 6/15/2020